

Notes of Survey.
 Crown Lands in Kaneohe Koolau poko Oahu

Plan of Survey.

(Continued from Page 151)

| BEARING | DISTANCES | | REMARKS | BEARINGS | | REMARKS |
|------------------|-----------|------|--|------------------|------|--|
| | CHAINS | FEET | | CHAINS | FEET | |
| 1. N. 77° 25' W. | 555 | | Along Punalui | N. 40° 50' E. | 494 | Along the line into Kanihau. This is a small angle of 115° 5' from the line to the next station. |
| 2. N. 41° 15' W. | 270 | | From station to the line | S. 84° 30' E. | 200 | |
| 3. N. 77° 25' W. | 280 | | From station to the line | | | |
| 4. S. 85° 20' E. | 974 | | From station to the line | | | |
| | | | Area 6 Acres | | | |
| | | | Lot D. | | | |
| | | | Wahialea Waho | | | |
| | | | Station point in corner marked with iron | | | |
| | | | From a small angle of 115° 5' from the line to the next station. | | | |
| | | | From station to the line | | | |
| | | | Station point | | | |
| 1. S. 50° 30' E. | 190 | | | 1. S. 22° 30' E. | 165 | |
| 2. N. 41° 15' W. | 280 | | Along Punalui | | | |
| 3. S. 62° 45' W. | 235 | | From station to the line | | | |
| 4. S. 50° 30' E. | 180 | | From station to the line | | | |
| | | | | | | |
| | | | Lot E. | | | |
| | | | Puuwaawe | | | |
| | | | Station point in corner marked with iron | | | |
| | | | From station to the line | | | |
| | | | Station point | | | |
| | | | From station to the line | | | |
| | | | Station point | | | |
| 1. S. 60° 45' W. | 200 | | | | | |
| 2. N. 40° 45' W. | 1000 | | Along Punalui | | | |
| 3. N. 25° 45' W. | 220 | | From station to the line | | | |
| 4. N. 40° 45' E. | 600 | | From station to the line | | | |
| | | | Station point | | | |
| 6. N. 60° 45' W. | 500 | | | | | |
| 7. S. 6° 10' E. | | | | | | |
| | | | | | | |
| | | | Lot F. | | | |
| | | | Wahialea Waho | | | |
| | | | Station point in corner marked with iron | | | |
| | | | From station to the line | | | |
| | | | Station point | | | |
| | | | From station to the line | | | |
| | | | Station point | | | |
| 1. S. 60° 45' W. | 200 | | | | | |
| 2. N. 40° 45' W. | 1000 | | Along Punalui | | | |
| 3. N. 25° 45' W. | 220 | | From station to the line | | | |
| 4. N. 40° 45' E. | 600 | | From station to the line | | | |
| | | | Station point | | | |
| 6. N. 60° 45' W. | 500 | | | | | |
| 7. S. 6° 10' E. | | | | | | |

www.information.com